

Application No.: A.25-06-017
Exhibit No.: Liberty-02-E **LIB-2E**
Witnesses:
T. Fee
G. Fowler
A. Lykens
E. Schwarzrock



(U 933-E)

Mountain View Fire Cost Recovery Application

Before the California Public Utilities Commission

Liberty-02: Ignition

Errata

(Clean Version)

Tahoe Vista, California

December 9, 2025

Liberty-02: Ignition

Table Of Contents

Section	Page	Witness
I. Executive Summary	1	E. Schwarzrock
II. The Mountain View Fire	2	T. Fee
A. The Fire Agency Investigation Was Not Sufficiently Thorough and Certain Conclusions in the Fire Agency Report Are Contradicted by the Evidence	3	
B. Shortcomings of the Investigation Aside, There is Evidence Consistent with the Ignition Having been Caused by Electrical Facilities and Such a Possibility Cannot be Ruled Out.....	6	
1. Eyewitness Testimony Indicates the Mountain View Fire Likely Started Adjacent to Liberty's Distribution Lines	6	
2. The Metallurgical Evidence Is Consistent with Conductor Contact and Separation.....	7	G. Fowler
3. Electrical Events Indicate that Liberty's Conductor Separated and Fell to the Ground Around the Time the Mountain View Fire Was First Reported	10	A. Lykens
C. Liberty's System Protection Scheme Operated as Expected in Response to the Electrical Events on the Day of the Ignition	10	

Liberty-02: Ignition

List of Figures

Figure	Page
Figure 1: Origin Area of the Mountain View Fire.....	2
Figure 2: Specific Origin Area Identified by Fire Agency Report, with the West and East Poles Marked	4
Figure 3: 12:01 p.m. Photograph of Specific Origin Area After Ignition.....	5
Figure 4: Simplified Illustration of Contact Points and Separation Location.....	9

I.

Executive Summary

This testimony sets forth Liberty’s analysis of the origin and cause of the Mountain View Fire that ignited on November 17, 2020, near the town of Walker, in Mono County, California. The fire was first reported at approximately 11:58 a.m. in a field alongside Highway 395 between the Mountain View Barbeque Restaurant and the Andruss Motel. The California Department of Forestry and Fire Protection (“Cal Fire”) conducted an investigation into the origin and cause of the fire and its findings are set forth in an investigation report, referred to throughout this testimony as the “fire agency report.”¹ As described in that report, Cal Fire concluded that the “most probable” cause of the fire was an energized conductor contacting the ground and igniting grassy fuels.²

In connection with the litigation arising from the Mountain View Fire, Liberty engaged an experienced wildland fire origin and cause expert to perform a technical peer review of the fire agency report and investigation. In his opinion, the fire agency investigation was not sufficiently thorough and did not meaningfully address conflicting witness statements. He notes that the ability of fire agency investigators to document and analyze fire movement indicators was limited due to rainfall in the area shortly after the ignition, and visual evidence of the early fire indicates the investigation likely identified an incorrect specific origin area.

Despite the investigation’s limitations and shortcomings, the possibility that electrical facilities caused the Mountain View Fire cannot be ruled out, and Liberty acknowledges there is evidence consistent with such a conclusion. An eyewitness reported seeing sparking from electrical facilities at Pole 266731 (the “West Pole”) and fire igniting near the base of that pole. After the fire ignited, one of Liberty’s conductors was found separated and on the ground between the West Pole and Pole 40288 (the “East Pole”), and post-incident examination of the conductor showed damage consistent with phase-to-phase contact at the area of separation. Liberty’s system protection also recorded electrical events on the circuit around the time of the reported ignition. Neither the fire agency investigation nor Liberty’s own investigation identified significant evidence showing an alternate cause of the Mountain View Fire.

¹ The fire agency report for the Mountain View Fire is Appendix A to this testimony.


² See Appendix A at 21.

II.

The Mountain View Fire

The Mountain View Fire ignited shortly before noon on November 17, 2020, near the town of Walker in Mono County, California. A 911 caller first reported the fire at approximately 11:58 a.m., and the fire was first observed in a grassy field adjacent to an area of Highway 395 that runs east and west. Cal Fire investigated the origin and cause of the Mountain View Fire and issued a report. Based on fire spread indicators, evidence collected, and witness statements, the report concludes that the “most probable” cause of the fire was an energized conductor contacting the ground and igniting grassy fuels between the East and West Poles.³ The origin area of the fire is shown in Figure 1.

Figure 1: Origin Area of the Mountain View Fire



While my review identified certain shortcomings with the fire agency investigation and report, there is evidence consistent with a power line-caused ignition. Eyewitnesses to the ignition and early stage of the fire reported first seeing fire near the base of the West Pole closest to the Andruss Motel, as well as sparking from Liberty's electrical facilities. After ignition, the northern field (C phase)

3 See Appendix A at 21.

1 conductor on the Topaz 1261 Circuit between the West and East Poles was found separated and lying in
2 the field near where the fire had ignited. Metallurgical examination of the conductors identified damage
3 consistent with phase-to-phase contact—specifically, fresh arc marks and melting of the steel core and
4 aluminum strands—at the point of separation. A protection device on Liberty’s system recorded
5 electrical faults on the Topaz 1261 Circuit around the time of the ignition consistent with phase-to-phase
6 contact and the conductor separation. Specifically, the 1261 R2 Recloser—the nearest protection device
7 upstream of the area of ignition—recorded a phase-to-phase fault before intermittent phase-to-ground
8 faulting. This phase-to-ground faulting caused the recloser to operate and ultimately lock out to de-
9 energize the line. In light of this evidence, Liberty acknowledges the possibility that its electrical
10 facilities were associated with ignition of the Mountain View Fire.

11 **A. The Fire Agency Investigation Was Not Sufficiently Thorough and Certain Conclusions in**
12 **the Fire Agency Report Are Contradicted by the Evidence**

13 I was engaged to perform a technical peer review of the fire agency investigation of the
14 Mountain View Fire. Based on that review, I conclude that the investigation was not thorough and
15 reached certain incorrect conclusions. The fire agency report acknowledged other “possible causes” of
16 the fire that were not ruled out, but nevertheless found that “an energized conductor contacting the
17 ground” was “the most probable cause of the Mountain View fire.”⁴ In my view, the fire agency
18 investigators did not conduct a sufficiently thorough investigation to rule out other potential causes of
19 the fire and, based on my peer review of their work, the cause of the fire should have been identified as
20 undetermined. The fire agency report notes that alternate ignition sources, such as arson or a
21 malfunctioning vehicle, remained possible causes, but investigators do not appear to have thoroughly
22 investigated alternate sources, notwithstanding the general origin area’s proximity to a heavily trafficked
23 highway. I believe it is possible the investigators’ initial observation that an electrical conductor had
24 separated and fallen to the ground resulted in expectation bias which impacted the investigation.

25 Properly identifying a specific origin area is a critical step in the wildland fire investigative
26 process. It is only after identifying a specific origin area that investigators should seek to identify the
27 cause of the ignition within that specific origin area. Here, the investigators did not conduct a broad
28 enough search to accurately identify a specific origin area. The only area the investigators appear to
29 have examined thoroughly was the area of the field where a section of damaged conductor was found

⁴ See Appendix A at 21.

1 lying on the ground adjacent to bleached rocks.⁵ The fire agency report indicates that investigators
2 mistakenly identified and focused on stains they thought were burn marks on rocks near this area and
3 indications of ignition, and failed to search for and consider further evidence. Smoke patterns on these
4 rocks, however, would have been indistinguishable between any arc flash and consumption of nearby
5 fuel by the fire, and were adjacent to vegetation that was consumed by the fire some time after its
6 ignition. Based on this, the fire agency report identified a specific origin area—a six feet by twelve feet
7 rectangular area near the end of the conductor and the burned rocks. This area is located between the
8 West and East Poles, just west of a parking turnout, as shown in Figure 2.⁶ This location, however,
9 appears unburned by an approaching flanking fire in photographic and video evidence captured by
10 eyewitnesses shortly after the fire began (Figure 3), further indicating that fire agency investigators did
11 not correctly identify the specific origin area of the fire.

Figure 2: Specific Origin Area Identified by Fire Agency Report, with the West and East Poles Marked



⁵ See Appendix A at 19.

⁶ See Appendix A at 20.

Figure 3: 12:01 p.m. Photograph of Specific Origin Area After Ignition



1 The fire agency investigation was complicated by environmental conditions, which impacted the
2 evidence available to fire agency investigators and, as a result, limited their ability to draw reliable
3 conclusions regarding the fire's origin and cause. High winds and rain in the area of origin following
4 ignition of the fire limited the quantity and availability of fire movement indicators that fire agency
5 investigators could analyze (though the rainfall aided fire suppression efforts, as described in *Liberty-04: External Factors*).⁷ This rainfall occurred before fire agency investigators arrived on scene the day
6 following the ignition, and may have limited their ability to draw reliable conclusions from the
7 remaining markers. In standard wildland fire investigations, investigators meticulously identify,
8 document, and analyze a large number of fire movement indicators in and around the suspected general
9 area of origin to understand the fire's movement and progression, as well as to identify the specific area
10 where it originated. In contrast, the number of fire movement indicators that fire agency investigators
11 documented and analyzed for the Mountain View Fire was quite small, which limited their ability to
12 draw reliable conclusions regarding the fire's specific origin area. It is also notable that one of the
13 investigators assisting the fire agency investigation identified ignition points that appear to be outside
14 the specific origin area identified by the fire agency report.

⁷ See Appendix A at 17 (“Extremely high winds on Tuesday, November 17, 2020, and prolonged rainfall overnight had eliminated any fire ash indicators in the fire areas I observed.”).

1 The investigators also failed to timely or thoroughly interview key witnesses. Early accounts by
2 eyewitnesses of the fire are conflicting in their description of the ignition's connection to electrical
3 facilities in the general vicinity where the ignition occurred. For instance, statements by certain
4 eyewitnesses suggested the fire started before the conductor separated and contacted the ground. One
5 eyewitness's testimony seemed to describe the field phase conductor separating and falling into the field
6 after the fire started. Another witness who described observing sparks fall from electrical equipment
7 from across Highway 395 testified that the fire started well before noon and that the conductors
8 remained in the air when the fire started. After later obtaining all of the relevant witness statements, the
9 investigators did not properly retest all possible hypotheses, or review phone records to establish a
10 timeline for the witness's observations. Particularly in light of potentially conflicting accounts, it is
11 critical for investigators to interview and document statements from all relevant eyewitnesses and
12 further develop evidence to help resolve the inconsistencies. Yet, based on my review of the
13 investigation, the fire agency investigators failed to interview some witnesses, and did not thoroughly
14 interview others. For instance, investigators do not appear to have interviewed the witness making the
15 initial 911 report, who did not reference electrical facilities in her report, or certain witnesses at the
16 nearby Mountain View Barbeque that captured key early photos and videos of the fire.

17 **B. Shortcomings of the Investigation Aside, There is Evidence Consistent with the Ignition**
18 **Having been Caused by Electrical Facilities and Such a Possibility Cannot be Ruled Out**

19 Notwithstanding the shortcomings of the fire agency investigation, I cannot rule out the
20 possibility of an ignition associated with electrical facilities based on the available evidence. There is
21 evidence consistent with the ignition having been caused by electrical facilities. Eyewitnesses reported
22 seeing the fire ignite near the base of the West Pole—an area more consistent with being a specific
23 origin area based on my review of the evidence. After the ignition, one of Liberty's conductors was
24 found separated and on the ground, and I understand metallurgical examination identified damage
25 consistent with phase-to-phase contact at the area of separation. Liberty's electrical event records also
26 indicate electrical faults on the Topaz 1261 Circuit around the time of the ignition consistent with phase-
27 to-phase contact and conductor separation.

28 **1. Eyewitness Testimony Indicates the Mountain View Fire Likely Started Adjacent to**
29 **Liberty's Distribution Lines**

30 Multiple eyewitnesses reported first identifying the fire near the base of the West Pole.
31 The caller who first reported the Mountain View Fire to 911 was located directly across

1 Highway 395 from the West Pole and described seeing flames that had just started, though there
2 was no specific mention of electrical facilities. Another eyewitness—potentially the first to
3 observe the Mountain View Fire—described hearing a noise, and turning to see sparks coming
4 down from the West Pole and flames and sparks around the base of the pole. Additionally, four
5 witnesses inside the nearby Mountain View Barbeque all reported seeing a small fire near the
6 West Pole. Each of the witnesses stated that they identified the fire shortly after the Mountain
7 View Barbeque lost power and they observed vehicles stop on Highway 395. One of those
8 eyewitnesses also reported seeing a power line moving chaotically in the air while sparking and
9 arcing.

10 Despite consistency in certain aspects of these witness observations, there also are
11 inconsistencies in other respects. The eyewitness who observed sparks falling from the West
12 Pole, for example, stated that all the power lines remained suspended in the air and reported first
13 seeing the fire at about 11:30 a.m., though phone records produced later in the litigation suggest
14 the time was likely around noon. Likewise, the witness who saw the power line chaotically
15 moving also described seeing the conductor come down into the field, which could suggest the
16 fire started before the conductor separation. Thus, some eyewitness accounts appear to suggest
17 that the fire may have started before nearby Liberty facilities were damaged. Notwithstanding
18 these inconsistencies, the eyewitness accounts of the incipient phase of the Mountain View Fire
19 are broadly consistent with an ignition located adjacent to and possibly caused by Liberty
20 facilities.

21 **2. The Metallurgical Evidence Is Consistent with Conductor Contact and Separation**

22 I was retained by Liberty to perform a metallurgical analysis of material related to the
23 Mountain View Fire. Following the fire, the field and center phase conductors between the West
24 Pole and East Pole near the origin area of the fire, as well as the triplex between the West Pole
25 and Service Pole, were removed for preservation, including both the conductors and splices that
26 were present on lines. I performed a site inspection of the origin area on December 5, 2023, and
27 attended an evidence examination of the preserved conductors at EAG Labs on December 7,
28 2023. I also understand that these conductors were the subject of earlier examinations at the
29 Bureau of Land Management in September 2021 and January 2022, as well as destructive testing
30 at EAG Labs in June 2023, and I reviewed photographs from these earlier examinations and
31 testing. From my review of the metallurgical evidence, I conclude that it is consistent with the


1 field and center phase conductors coming into contact and arcing on the day of the Mountain
2 View Fire, with the field phase subsequently separating and falling to the ground. The
3 separation of the field phase conductor was caused by melting due to arcing.

4 The center and field phase conductors show evidence of recent arcing consistent with
5 phase-to-phase contact on November 17, 2020. The area of contact was approximately mid-span
6 between the West and East Poles, including at the location where the field phase conductor
7 ultimately separated and fell to the ground.⁸ The field phase conductor exhibited arcing and
8 melting on each end of the separation point. In particular, there was melting on every aluminum
9 strand at all points of separation, including the steel core strand. The lack of oxidation and
10 overall appearance of this evidence indicates that the damage is fresh and occurred shortly before
11 the conductor was removed from the field. The center phase conductor also exhibited areas of
12 arcing. The most pronounced area aligns with the location of the field phase conductor
13 separation, indicating that the two conductors came into contact. Unlike the field phase
14 conductor, however, the steel core of the center phase conductor remained intact and the
15 conductor did not separate or fall to the ground, though some of the individual aluminum strands
16 separated due to arcing and melting. The center and field phases did not exhibit evidence of old
17 arcing.

18 The west end of the field phase conductor also exhibited discoloration, likely due to the
19 ground fire. The evidence indicates the west side of the field phase conductor contacted another
20 metal wire—likely the bare neutral wire associated with the triplex conductor between the West
21 Pole and a service pole to its north and a guy wire supporting the West Pole. The east end of the
22 field phase conductor exhibited mechanical damage. The conductor east of the separation point
23 was de-energized due to the separation and apparently fell to the ground in a gravel parking area,
24 where I understand it was driven over by multiple vehicles.

⁸ The conductor's point of separation was approximately 135 feet, 8 inches from the West Pole.

Figure 4: Simplified Illustration of Contact Points and Separation Location



1 Although a metallurgist retained by plaintiffs in the civil litigation suggested the field
2 phase conductor separated due to fatigue,⁹ that conclusion is not supported by the metallurgical
3 evidence. In particular, fatigue results in striations and beachmarks that are clearly identifiable
4 on the fracture surface.¹⁰ Yet no striations or beachmarks were present on the ends of the strands
5 of the field phase conductor, and my review of the evidence showed no sign of separation due to
6 fatigue. A fatigue separation also is unlikely in light of the strength of the materials comprising
7 the ACSR and forces on the conductor between the East and West Poles. The strength of the
8 ACSR conductor far exceeded the applied forces, and the strength of the steel core alone is more
9 than sufficient to support the conductor for a span between the West and East Poles, even during
10 windy conditions such as on November 17, 2020.

⁹ Fatigue is a progressive mode of crack growth that occurs in small increments due to cyclic stresses of sufficient magnitude and duration.

¹⁰ Russell A. Lund & Shahram Sheybany, “Fatigue Fracture Appearances” ASM Handbook, Vol. 11 (Metals Handbook article).

1 My metallurgical review of the evidence is consistent with the center and field phase
2 conductors coming into contact and arcing, resulting in separation of the field phase conductor.

3 **3. Electrical Events Indicate that Liberty's Conductor Separated and Fell to the**
4 **Ground Around the Time the Mountain View Fire Was First Reported**

5 As detailed more fully below in Section C, post-incident analysis of Liberty's electrical
6 event records from the 1261 R2 Recloser—the closest upstream protective device to the facilities
7 near the area of origin—indicates that at approximately 11:55 a.m. on November 17, 2020, the
8 1261 R2 Recloser recorded a phase-to-phase fault followed by a series of ground faults. These
9 electrical events recorded on the Topaz 1261 Circuit are consistent with the center and field
10 phase (B phase and C phase) conductors between the West and East Poles coming into contact
11 and arcing, with the field phase (C phase) then separating and falling to the ground. These
12 events occurred three minutes before the Mountain View Fire was first reported by a 911 caller
13 from across Highway 395. I understand the 911 caller indicated that the fire looked like it had
14 just started and was moving fast, but did not make any reference to power lines or a cause.

15 **C. Liberty's System Protection Scheme Operated as Expected in Response to the Electrical**
16 **Events on the Day of the Ignition**

17 Review of electrical event records indicates that Liberty's system protection scheme operated as
18 expected in response to faults on the Topaz 1261 Circuit on November 17, 2020. As described in more
19 detail in *Liberty-03: Prudence of Operations*, the Topaz 1261 Circuit originates at an NV Energy
20 substation in Nevada and Liberty's facilities begin at the California-Nevada border. Liberty's portion of
21 the Topaz 1261 Circuit was protected by two line reclosers, referred to as the 1261 R1 and 1261 R2
22 Reclosers. The 1261 R1 Recloser was located near the border and the beginning of Liberty's facilities
23 on the Topaz 1261 Circuit. The 1261 R2 Recloser was the nearest upstream line recloser between the
24 1261 R1 Recloser and the West and East Poles. Following the fire, electrical event records were
25 downloaded from the reclosers and analyzed by Liberty.

26 Liberty's protection system functioned properly to interrupt the fault current and de-energize the
27 portion of the circuit past the 1261 R2 Recloser once the field phase (C phase) conductor separated and
28 fell to the ground between the East and West Poles, as noted in Section II.B.3 above. At approximately
29 11:55:08 a.m., the 1261 R2 Recloser recorded a 295-amp phase-to-phase fault between the center and
30 field phases (B phase and C phase). This fault cleared without exceeding time-current curve settings
31 and therefore did not prompt operation of the 1261 R2 Recloser. Approximately two seconds later, the

1261 R2 Recloser began detecting a series of phase-to-ground faults on the field phase (C phase) as the
2 broken conductor contacted the ground in the field. Ground faults are by nature chaotic with respect to
3 their fault currents, due to the fact that the energized conductors are moving and the earth is a poor
4 conductor. The 1261 R2 Recloser was in normal operating mode at the time, which provides for three
5 relay operations before locking out, as described further in *Liberty-03*. At approximately 11:55:43 a.m.,
6 thirty-two seconds after the initial ground fault, the 1261 R2 Recloser operated and locked out, de-
7 energizing the Topaz 1261 Circuit downstream of the 1261 R2 Recloser.

8 Liberty's system protection also quickly responded to activity on the circuit earlier in the day on
9 November 17, 2020. Specifically, the 1261 R2 Recloser recorded a B phase to C phase fault around
10 9:48 a.m.¹¹ Because work was being performed on the circuit at that time, the 1261 R2 Recloser
11 operated in response to that fault to de-energize the line downstream of that location and did not attempt
12 to reclose and re-energize the line.¹² In response, field personnel patrolled the Topaz 1261 Circuit
13 downstream of the 1261 R2 Recloser to the end of the line, including the subject span between the East
14 Pole and West Pole. As a precaution, field personnel removed slack from a stretch of the Topaz 1261
15 Circuit located northwest of the West and East Pole. These fifteen spans were in "hot arms" due to the
16 ongoing reconductoring work. At approximately 10:41 a.m., the 1261 R2 Recloser was closed to restore
17 power to Liberty customers.¹³

¹¹ A limited earlier outage occurred at 8:35 a.m. upstream of the 1261 R2 Recloser. No fault was recorded, but a cutout was found open.

¹² The 1261 R2 Recloser did not attempt to reclose following this fault because "hotline tag" settings were active at the time due to the reconductoring work being performed on the circuit that morning.

¹³ In coordination with field personnel performing the reconductoring work, the "auto" or normal setting was selected when the 1261 R2 Recloser was closed. See *Liberty-03: Prudence of Operations* for a more detailed discussion of Liberty's system protection and operating procedures. Subsequent review of recloser records following the fire also identified a transient phase-to-phase fault recorded by the 1261 R2 Recloser at approximately 10:53 a.m. on November 17, 2020. The fault current was of insufficient magnitude and duration for the recloser to operate and the fault self-cleared.

Appendix A

CAL FIRE



CALIFORNIA DEPARTMENT OF FORESTRY AND FIRE PROTECTION SAN BERNARDINO-INYO-MONO UNIT

3800 N. Sierra Way
San Bernardino, California 92405
(909) 881-6900

INVESTIGATION REPORT

CASE NUMBER:

20CAOVD030860

CASE NAME:

MOUNTAIN VIEW

DATE:

November 17, 2020

INCIDENT TYPE:

Wildland

INCIDENT INVESTIGATORS:

Joseph PIDGEON, Battalion Chief, BDU

Mathew KIRKHART, Fire Captain, BDU

1 **1 - VIOLATIONS:**

2

3 Penal Code § 452 A person is guilty of unlawfully causing a fire when he recklessly sets
4 fire to or burns or causes to be burned, any structure, forest land or property.

5 (a) Unlawfully causing a fire that causes great bodily injury is a felony punishable by
6 imprisonment in the state prison for two, four or six years, or by imprisonment in the
7 county jail for not more than one year, or by a fine, or by both such imprisonment and
8 fine.

9 (b) Unlawfully causing a fire that causes an inhabited structure or inhabited property to
10 burn is a felony punishable by imprisonment in the state prison for two, three or four
11 years, or by imprisonment in the county jail for not more than one year, or by a fine, or
12 by both such imprisonment and fine.

13 (c) Unlawfully causing a fire of a structure or forest land is a felony punishable by
14 imprisonment in the state prison for 16 months, two or three years, or by imprisonment
15 in the county jail for not more than six months, or by a fine, or by both such
16 imprisonment and fine.

17 (d) Unlawfully causing a fire of property is a misdemeanor. For purposes of this
18 paragraph, unlawfully causing a fire of property does not include one burning or causing
19 to be burned his own personal property unless there is injury to another person or to
20 another person's structure, forest land or property.

21

22 Penal Code § 454 (a)(2) Every person who violates Section 451 or 452 during and
23 within an area of any of the following, when proclaimed by the Governor, shall be
24 punished by imprisonment in the state prison, as specified in subdivision (b):

25 (2) A state of emergency pursuant to Section 8625 of the Government Code.

26

27 Penal Code § 192 Manslaughter is the unlawful killing of a human being without malice.

28 (b) Involuntary—in the commission of an unlawful act, not amounting to a felony; or in
29 the commission of a lawful act which might produce death, in an unlawful manner, or
30 without due caution and circumspection. This subdivision shall not apply to acts
31 committed in the driving of a vehicle.



1 Public Resources Code § 4421 A person shall not set fire or cause fire to be set to any
2 forest, brush, or other flammable material which is on any land that is not his own, or
3 under his legal control, without the permission of the owner, lessee, or agent of the
4 owner or lessee of the land.

5

6 Public Resources Code § 4422(b) A person shall not do any of the following:
7 (b) Allow any fire kindled or attended by him to escape from his control or to spread to
8 the land of any person other than from the land from which the fire originated.

9

10 Public Utilities Code § 8386(a) Each electrical corporation shall construct, maintain,
11 and operate its electrical lines and equipment in a manner that will minimize the risk of
12 catastrophic wildfire posed by those electrical lines and equipment.

13

14 Public Utilities Commission, General Order 95; Rule 31.1 Design, Construction and
15 Maintenance Electrical supply and communication systems shall be designed,
16 constructed, and maintained for their intended use, regard being given to the conditions
17 under which they are to be operated, to enable the furnishing of safe, proper, and
18 adequate service. For all particulars not specified in these rules, design, construction,
19 and maintenance should be done in accordance with accepted good practice for the
20 given local conditions known at the time by those responsible for the design,
21 construction, or maintenance of communication or supply lines and equipment. A supply
22 or communications company is in compliance with this rule if it designs, constructs, and
23 maintains a facility in accordance with the particulars specified in General Order 95,
24 except that if an intended use or known local conditions require a higher standard than
25 the particulars specified in General Order 95 to enable the furnishing of safe, proper,
26 and adequate service, the company shall follow the higher standard. For all particulars
27 not specified in General Order 95, a supply or communications company is in
28 compliance with this rule if it designs, constructs and maintains a facility in accordance
29 with accepted good practice for the intended use and known local conditions. III-6
30 January 2015 Rule 31.1 All work performed on public streets and highways shall be
31 done in such a manner that the operations of other utilities and the convenience of the

1 public will be interfered with as little as possible and no conditions unusually dangerous
2 to workmen, pedestrians or others shall be established at any time.

3

4 Health and Safety Code § 13001 Every person is guilty of a misdemeanor who, through
5 careless or negligent action, throws or places any lighted cigarette, cigar, ashes, or
6 other flaming or glowing substance, or any substance or thing which may cause a fire,
7 in any place where it may directly or indirectly start a fire, or who uses or operates a
8 welding torch, tar pot or any other device which may cause a fire, who does not clear
9 the inflammable material surrounding the operation or take such other reasonable
10 precautions necessary to insure against the starting and spreading of fire.

11

12 Health and Safety Code § 13007 Any person who personally or through another wilfully,
13 negligently, or in violation of law, sets fire to, allows fire to be set to, or allows a fire
14 kindled or attended by him to escape to, the property of another, whether privately or
15 publicly owned, is liable to the owner of such property for any damages to the property
16 caused by the fire.

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32



1 **2 - SUMMARY:**

2

3 On Tuesday, November 17, 2020, at approximately 12:09 PM, resources from
4 the Bureau of Land Management, Owens Valley District (OVD), the United States
5 Forest Service, Humbolt-Toyaibe National Forest (HTF), and the Antelope Valley Fire
6 Protection District responded to a reported vegetation fire in the 100000 block of
7 Highway 395, in the community of Coleville, located in Mono County California.

8

9 The wildland fire consumed 20,835 acres of vegetation and watershed, as well
10 as 96 residential structures and one commercial building. One civilian fatality occurred
11 during the fire. The fire was ignited by energized conductor separating, and arcing
12 while in contact with the ground; igniting dead annual grasses.

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32



1 **3 – SUSPECT/SUBJECTS:**

2

3 **S-1** Liberty Utilities
4 701 National Avenue
5 PO Box 107
6 Tahoe Vista, CA 96148
7 (530) 546-1741

8

9 **SB-1** [REDACTED]
10 Supervisor
11 Liberty Utilities
12 701 National Avenue
13 Tahoe Vista, CA 96148
14 (530) 546-1741

15

16

17 **SB-2** [REDACTED]
18 [REDACTED]
19 Liberty Utilities
20 701 National Avenue
21 Tahoe Vista, CA 96148
22 (530) 546-1741

23

24

25

26

27

28

29

30

31

32



1 **4 - VICTIMS & WITNESSES:**

2

3 V-1 [REDACTED]

4

5

6 *See Mono County Sheriff report for further information.*

7

8 V-2 thru V-132 (see attachment 8 for complete list from Mono County)

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

1 W-1 [REDACTED] DOB: [REDACTED]
2
3

Owner of the Mountain View Barbeque Restaurant and victim of the fire.

5
6 W-2 [REDACTED] DOB: [REDACTED]
7 CA DL: [REDACTED] expires [REDACTED]
8 [REDACTED]
9
10 HT: [REDACTED] WT: [REDACTED]
11 HAIR: [REDACTED] EYES: [REDACTED]
12 [REDACTED] cell

Employee at Mountain View Barbeque Restaurant. Working at the Mountain View Barbeque Restaurant during discovery of the fire.

15
16 W-3 [REDACTED] DOB: [REDACTED]
17 CA DL: [REDACTED] expires [REDACTED]
18 [REDACTED]
19 [REDACTED]
20 [REDACTED]
21 HT: [REDACTED] WT: [REDACTED]
22 HAIR: [REDACTED] EYES: [REDACTED]

Daughter of [REDACTED]. Working at the Mountain View Barbeque Restaurant during discovery of the fire.

25
26 W-4 [REDACTED] DOB: [REDACTED]
27
28
29

Saw smoke, over the roof lines, from her house and drove to the area of the smoke. Saw power company employee cut the downed lines.

1 W-5 [REDACTED] DOB: [REDACTED]
2 CA DL: [REDACTED]
3 [REDACTED]
4 [REDACTED]
5 [REDACTED]
6 HT: [REDACTED] WT: [REDACTED]
7 HAIR: [REDACTED] EYES: [REDACTED]

Observed glowing items falling from power lines and fire in cured annual grasses ignite. Provided Ring camera footage from prior to the fire ignition.

Initial Attack Incident Commander (IC) for the Mountain View fire.

Incident Public Information Officer (PIO) for the Mountain View fire.

W-8 Rich NALDER, Fire Chief
Antelope Valley Fire Protection District
1166 Larson Lane
Coleyville, CA 96107

Unified Incident Commander for the fire within his fire protection district.

W-9 Mark HANSON, Lieutenant
Mono County Sheriff Department
49 Bryant Street
Bridgeport, CA 93517

Law enforcement liaison. Death investigation contact for Mountain View fire fatality.

W-10 Mathew KIRKHART, Fire Captain Specialist
California Department of Forestry and Fire Protection (CAL FIRE)
3800 North Sierra Way
San Bernardino, CA 92405

Investigator. Assisted with origin and cause investigation.

W-11 Joseph PIDGEON, Battalion Chief
California Department of Forestry and Fire Protection (CAL FIRE)
3800 North Sierra Way
San Bernardino, CA 92405

Lead investigator, conducted origin and cause investigation.

1 **5 - EVIDENCE:**

2

3 Photographs P-JP-001 thru P-JP-049.

4

5 Photographs P-MK-001 thru P-MK-024.

6

7 Cell phone photograph from [REDACTED]

8

9 Cell phone photographs from [REDACTED]

10

11 "Ring" camera footage, prior to power failure, from [REDACTED]

12

13 Evidence Item #1 – Power line cable (Conductor). East end of cable found on ground.

14 Outside phase, field side of power lines. Collected by J. PIDGEON on 11/18/20.

15

16 Evidence Item #2 – Power line cable (Conductor). West end of cable found on ground.

17 Outside phase, field side of power lines. Collected by J. PIDGEON on 11/18/20.

18

19 Evidence Item #3 – Power line cable (Conductor). Center phase of cable. Section

20 secured by power company for CAL FIRE. Collected by J. PIDGEON on 11/18/20.

21

22

23

24

25

26

27

28

29

30

31

32

1 Peak wind speeds on Tuesday, November 17, 2020, as recorded by the Walker
2 (WALC1) RAWS included wind speeds of 38 miles per hour, with gusts of 73 miles per
3 hour.

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32



1 **7 – EQUIPMENT:**

2

3 Power pole

4 #34334-CIT

5

6 Power pole

7 #266731

8

9 Conductor segments between pole number 34334-CIT and 266731.

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32



1 **8 - PROPERTY:**

2 State, local, and federal lands were affected. Multiple parcels in the Walker and
3 Coleville communities of Mono County. See attachment 8 for parcel list from Mono
4 County Assessor's office.

5

6 See attachment 7 for overall land ownership map (State, Local, Federal).

7

8 See attachment 8 for Assessor Parcel Number list and owner information.

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32



1 **9 - NARRATIVE:**

2 On Tuesday, November 17, 2020, at approximately 12:09 PM, resources from
3 the Bureau of Land Management, Owens Valley District (OVD), The United States
4 Forest Service, Humbolt-Toyaibe National Forest (HTF), and the Antelope Valley Fire
5 Protection District responded to a reported vegetation fire in the 100000 block of
6 Highway 395, in the community of Walker/Coleville, located in Mono County, California.

7 I was requested, via telephone, from the California Department of Forestry and
8 Fire Protection (CAL FIRE) Emergency Command Center in San Bernardino, California,
9 to respond as a fire investigator at approximately 5:00 PM. I arrived at the fire scene
10 Wednesday, November 18, 2020, at approximately 1:45 AM. I contacted the incident
11 Night Operations Chief and confirmed the morning briefing time and location before
12 finding lodging for the night.

13

14 Wednesday, November 18, 2020, I attended the 7:00 AM incident briefing at the
15 Antelope Valley Fire Protection District fire station on Larson Road. The Incident
16 Commander (IC) advised the fire was approximately 20,000 acres in size; had damaged
17 or destroyed an estimated 80 homes; and one civilian fatality had occurred.

18 I contacted Lieutenant Mark HANSON of the Mono County Sheriff Department at
19 the briefing location. HANSON was coordinating the law enforcement resources. I
20 confirmed that the civilian fatality had been recovered and my origin and cause
21 investigation would not interfere with the death investigation. HANSON confirmed the
22 body had been recovered and I would not interfere with any death investigation scene. I
23 checked in with the Incident Commander (IC) Erik NEWELL, incident Public Information
24 Officer (PIO) Jennifer DIAMOND, and Fire Chief Rich NALDER of the Antelope Valley
25 Fire Protection District before traveling to the dispatched location of the fire.

26 I arrived at the 107000 block of Highway 395. I parked at the Walker Burger
27 restaurant. I walked the perimeter of the restaurant and did not observe any indicators
28 of a fire. I drove north, to the intersection of East Mill Creek Lane and Meadow Drive. I
29 observed foliage freeze on trees indicating the fire had advanced from southeast of my
30 location. I moved again to the east side of the Mountain View Barbeque restaurant
31 located at 106834 Highway 395. As I traveled to the Mountain View Barbeque
LE80 (Rev. 7/2011)



1 restaurant, I observed burned vegetation adjacent to the highway. I parked my vehicle,
2 in an unburned area, east of the Mountain View Barbeque restaurant. I began an
3 observation of the area to establish my General Origin Area (GOA). I began walking in
4 a counterclockwise direction observing macro fire indicators. I walked north to an
5 access road and continued north until reaching Meadow Drive. I traveled west along
6 Meadow Drive to the property fence line at Springer Court. I walked south along fence
7 line to Highway 395 and then east along Highway 395 until returning to my vehicle. I
8 then walked in a counterclockwise direction around the burned area adjacent to
9 Highway 395. I determined this area to be my General Origin Area (GOA).

10 Extremely high winds on Tuesday, November 17, 2020, and prolonged rainfall
11 overnight had eliminated any fire ash indicators in the fire areas I observed.

12 I observed power poles and power distribution equipment along the southern
13 edge of the general origin area (see photos P-JP-004 thru P-JP-013 and P-JP-016 thru
14 P-JP-023). Both power poles were in compliance with California Public Resource Code
15 (PRC) Section 4292 and PRC Section 4993 requirements. Segments of cable, later
16 identified as conductor segments from the adjacent power poles, were observed in the
17 roadside turnout and inside the burn area north of Highway 395 (see photos P-JP-010
18 thru P-JP-013). I observed staining on large rocks (see photos P-JP-013 thru P-JP-
19 015). An additional piece of cable, later identified as a conductor segment, was
20 observed in the burned area between the power poles adjacent to Highway 395 and the
21 burned area (see photos P-JP-018 thru P-JP-023). I observed "U" shaped burn
22 patterns in the cured annual grasses located in the open field (see photos P-JP-038 thru
23 P-JP-040, P-JP-043 thru P-JP-044), and burned brush within the perimeter of the burn
24 area.

25 During my observation of the GOA, random private vehicle traffic began to
26 increase in the roadside turnout and the access road. I moved my vehicle adjacent to
27 mailboxes in front of the Mountain View Barbeque restaurant and placed surveyors
28 flagging along Highway 395 to prevent further traffic through the area and resume
29 observations.

30 While walking the perimeter of my GOA, I did not observe security cameras on
31 the exterior of the Mountain View Barbeque restaurant, the Walker Burger restaurant, or
LE80 (Rev. 7/2011) 17 Officer Initials [REDACTED]

1 the Shadows Crafts business.

2 I observed a [REDACTED], later identified as [REDACTED] (W-2), park
3 his vehicle and walk to the front of the restaurant. I contacted [REDACTED] and
4 interviewed him about the fire. During my interview, the owner of the Mountain View
5 Barbeque restaurant, later identified as [REDACTED] (W-1), and [REDACTED]
6 [REDACTED] (W-3), arrived and contributed statements. [REDACTED] provided a cell phone photo
7 she took with her cell phone (see attachment 7). The photo is from the front porch area
8 of the restaurant, looking west.

9

10 *The following is a summary of the interview with [REDACTED] on*
11 *Wednesday, November 18, 2020. [REDACTED] contributed statements during my*
12 *initial interview with [REDACTED]:*

13 All three persons were working at the Mountain View Barbeque restaurant. The
14 power was off, but they were cleaning inside the restaurant. All three persons
15 commented on the strength of the winds. All three said they had never observed winds
16 that strong in the area. The power returned for approximately twenty minutes before
17 shutting off again. [REDACTED] said she had received text message notifications from Liberty
18 Utilities about the power outage. As they continued to clean, they noticed vehicles
19 stopping in front of the restaurant. They saw passengers recording with their cell
20 phones. [REDACTED] looked out of a front window from the restaurant, towards the direction
21 the vehicles were recording. [REDACTED] saw a fire in the grass area, west of the restaurant
22 and north of Highway 395. [REDACTED] exited the restaurant and took a photo with her cell
23 phone (see attachment 7). [REDACTED] and [REDACTED] said they saw a downed power line
24 arcing in the parking lot (roadside turnout). [REDACTED] said there was no security camera
25 footage from the restaurant.

26

27 Vehicles marked with Liberty Utilities logos stopped near the west power pole
28 and visually surveyed the power pole and equipment. I approached them and provided
29 my contact information for their supervisor. I was later contacted by Liberty Utilities
30 Area Supervisor, [REDACTED], and [REDACTED], Senior Manager, Wildfire
31 Prevention for Liberty Utilities via my cell phone. Records including customer
LE80 (Rev. 7/2011)



1 notifications, and notification methods utilized, as well as company records for any
2 faults, and/or power disruption notifications were requested for a time period of
3 approximately four hours prior to the 911 report of the Mountain View fire on Tuesday,
4 November, 17, 2020 (see attachment 21 for documents produced). When asked,
5 [REDACTED] said Liberty Utilities had not conducted a Public Safety Power Shutdown
6 (PSPS) prior to the fire.

7 Fire Captain Specialist Matt KIRKHART arrived at the GOA and assisted with the
8 survey of the GOA. KIRKHART and I walked approximately 30 yards north of the
9 roadside turnout, on the access road, on the east side of the open field. We entered the
10 fire area where advancing fire spread indicators were present, and began walking west
11 and east, in a zig-zag pattern observing macro and micro fire spread indicators. We
12 utilized colored flags to indicate fire spread indicators. We utilized red for advancing fire
13 spread indicators, yellow for lateral fire spread indicators, blue for backing fire spread
14 indicators, lime-green for items of interest, and white for evidence items in accordance
15 with NWCG FI-210 standards.

16 I observed advancing fire spread indicators within the open field north of Highway
17 395, and west of the Mountain View Barbeque restaurant. I observed angle of char, an
18 advancing fire spread indicator, on brush (see photo P-JP-032). I observed additional
19 angle of char, advancing fire spread indicators, on grass clumps north of Highway 395,
20 indicating the fire burned from south to north. I observed staining on the large rocks
21 west of the roadside turnout (see photo P-JP-013 thru P-JP-015), an advancing fire
22 spread indicator. We walked west, past the large rocks with staining, and observed
23 white marks on the ground. The rocks appeared to be bleached (see photos P-MK-003,
24 P-MK-004, and P-MK-006). The group of bleached rocks were indicated with white
25 green flags. The rocks surrounding the bleached rocks appear to be crushed lava
26 rocks. The bleached rocks appeared to be the same type, but discolored due to contact
27 with high heat. We observed a section of conductor cable in the area of the bleached
28 rocks. We observed a section with "bird caging" (see photos P-MK-019 and P-MK-020).
29 I observed beading and melted areas consistent with arcing and high heat on the
30 section of conductor cable identified as evidence #2. The conductor segment appeared
31 to have been cut on the west end (see photo P-JP-018 thru P-JP-020). The
LE80 (Rev. 7/2011)

1 continuation segment had been secured to the power pole (see photo P-JP-021 thru P-
2 JP-023). The east end of the conductor appeared to have melted and separated from
3 the east conductor segment (see photo P-JP-049) collected as evidence item # 1. I
4 determined my Specific Origin Area (SOA) to be approximately six feet across (south to
5 north) and approximately twelve feet wide (west to east). The SOA was located north of
6 the Highway 395 easement within the cured annual grass area, east of power pole
7 #266731, and west of the roadside turnout.

8 Visual observation of the overhead power lines, we observed a damaged spot on
9 the conductor cable. The damage appeared to be melted and charring was visible from
10 the ground. The damage appeared to be located on the lateral side of the conductor
11 cable, on the north side of the conductor cable. KIRKHART photographed colored flags
12 within the GOA, and other items of interest. Utilizing a magnet in a zig-zag pattern,
13 KIRKHART gridded the SOA. No items were collected by the magnet. No molten metal
14 items were observed in the SOA, or GOA. A segment of the center phase conductor
15 approximately twenty feet long was collected with the assistance of Liberty Utilities and
16 their contractors as evidence item #3. I collected evidence items #1 thru #3 and
17 secured them in my CAL FIRE vehicle. Surveyors flagging was removed, colored flags
18 collected and the origin area was released back to the incident.

19
20 *The following is a summary of the telephone interview with [REDACTED] on*
21 *Tuesday, December 29, 2020. [REDACTED] provided a written statement of her*
22 *observations (see attachment 11).*

23 [REDACTED] was outside at her business, located at 106979 Highway 395 in
24 Coleville, California. [REDACTED] heard a loud noise and looked in the direction of the
25 noise and saw glowing items falling to the ground. The glowing items appeared to be
26 falling from power lines located across the highway from her business. The glowing
27 items fell into the cured annual grasses. [REDACTED] saw flames as the cured annual
28 grasses began to burn. [REDACTED] said the wind spread the fire very rapidly in the field of
29 cured annual grasses. [REDACTED] said the two video clips from her "Ring" camera cut out
30 at the time power was lost and the wifi connection to her cameras was lost.

31

1 CONCLUSION

2 No cigarette butts, or other smoking materials were observed in the general or
3 specific origin areas (Note: Temperature must be above 80 degrees Fahrenheit and the
4 Relative Humidity must be below 22 for a cigarette to be considered.). While the
5 Relative Humidity was below 22%, the temperature recorded at the Walker RAWs was
6 66 degrees Fahrenheit. I did not observe railroad tracks, or other indicators of tractors,
7 or heavy motorized equipment operating in the area. No reports of lightning occurred in
8 the area. I did not observe evidence of pile burning or rock rings for campfires. I did not
9 observe piled organic materials consistent for spontaneous combustion, nor did I
10 observe materials, such as broken glass, consistent with light refraction in the SOA.

11 Arson and a malfunctioning highway vehicle are possible causes, due to the
12 proximity of Highway 395 and easy access from the roadway, however fire spread
13 indicators, evidence collected, and witness statements support the most probable
14 conclusion of an energized conductor contacting the ground as the most probable
15 cause of the Mountain View fire.

16 I believe based on my training and experience the most probable cause of the
17 Mountain View fire was ignition of cured annual grasses, due to a spark from a down,
18 energized, conductor contacting the ground. Extremely high winds and low relative
19 humidity contributed to the rapid spread of the fire.

20 I reserve the right to amend this report as necessary upon discovery of additional
21 information and/or additional evidence.

22
23
24
25
26 Joe Pidgeon, Battalion Chief
27 CAL FIRE - BDU
28 3800 North Sierra Way
29 San Bernardino, CA 92405
30
31
32

1 **10 - ATTACHMENTS:**

2

3 1. Wild CAD Log from Sierra Front Interagency Dispatch Center (NV-HTF)

4 2. Photographs P-JP-001 thru P-JP-049 taken by Joe PIDGEON

5 3. Photographs P-MK-001 thru P-MK-024 taken by Matt KIRKHART

6 4. Remote Area Weather Station (RAWS) – Walker RAWS

7 5. Google maps of origin area

8 6. Fire perimeter map

9 7. Fire perimeter map with land ownership (State, Local, Federal)

10 8. Damage inspection notes from Mono County

11 9. Matt KIRKHART sketch

12 10. Matt KIRKHART Supplemental (LE-71 form)

13 11. Witness Statement LE78 from [REDACTED]

14 12. Cell phone photograph from [REDACTED]

15 13. Cell phone photographs from [REDACTED]

16 14. [REDACTED] Ring camera footage

17 15. Emergency Proclamations – State of California

18 16.

19 17.

20 18.

21 19.

22 20.

23 21. Liberty Utilities documents

24 22. Property Receipt (CAL FIRE LE-92 form) for power line cables collected.

25 23. California Public Utilities Commission (CPUC) Evidence Inspection

26 Agreement

27 24. KIRKHART thumbnails

28 25. Thumbnails

