

Application No.: A.25-06-017
Exhibit No.: LIB-40



(U 933-E)

Mountain View Fire Cost Recovery Application

Exhibit LIB-40

1261 November 17, 2020 Switching Log

PUBLIC



Switch Person	Activity	Time
	1261 R2 LOCKOUT (B:CP/OC)	17 NOV '20 12:49
	Under NRA	
	Per [REDACTED] - they were not in the air - very windy	
	Slack removed CP40271	
SCADA	1261 P293295 HWY 395	
	1261 R2, Check RIR off	17 NOV '20 13:43
	1261 Close 1261 R2, Put R/R on	17 NOV '20 13:45
		14:55
	1261 R2 L/O	17 NOV '20 14:58
	Trip close x7; CØ:GNDoc	
	Contacted [REDACTED] to patrol	17 NOV '20 14:57
	Report of line down & cut clear.	
	1261 HWY 395 between	17 NOV '20 15:12
	bell P4840284 & P78836 (East Mill Creek Rd)	
	Fire started, moving	



Switch Person	Activity	Time
	contacted [REDACTED] Re: Fire Season - agreed to Put R1 in fire (R/R off)	15:27
	on 1261 @ P195632 Hwy 395. Put 1261 R1 R/R off.	15:30 15:28
	Per [REDACTED] - opening fuses @ P16218 Feeding Larson Lane due to spreading fire concerns	15:29
[REDACTED]	P16218 c/o opened checked open : tagged (de-energized area behind fire)	17 NOV '20 15:50
	[REDACTED] advised. want 1261 R1 open	17 NOV '20 15:51
(B) SCADA	1261, P195632 Hwy 395 check R/R off, open 1261 R1	